




U00980010223D222C33290A69662872656631213D,  
U00A8001030290A7B0A0A69662850436F64653D3D,  
U00B80010222290A7B0A50436F64653D4D696428,  
U00C80010444C5061727365537472696E672C7265,  
U00D8001066312B31352C35290A7D0A7D0A7D0A0A,  
U00E800104F5554312E446174613D22222B225C74,  
U00F80010222B4C4E616D652B225C74222B464E61,  
U010800106D652B225C74222B42697274684D6E2B,  
U01180010222F222B426972746844792B222F222B,  
U01280010426972746859342B225C745C745C7422,  
U013800102B53747274312B225C74222B53747274,  
U01480010322B225C74222B436974792B225C7422,  
U015800102B53746174652B225C74222B50436F64,  
U01680010652B225C625C625C625C625C74220A0A,  
U01780010446F534C46284F555431290A7D0A7D0A,  
U018800100A0A2443444C454E30310A2443444C46,  
U0198001053303130393032313830313039303231,  
U01A8001041303130393032303730313246303230,  
U01B8001036303132463032303930313039303130,  
U01C8001039303130393032303530313039303232<CR>

BayScan Technologies LLC  
**CONFIDENTIAL**



ule 31,ule 32,ule 33,ule 34

~3\$U01D8001030303130393032303130313039303230,  
U01E8001034303130393032303330313038303130,  
U01F8001038303130383031303830313039303030,  
U02080004300A040A<CR>



Exit Configuration

~3\$P<CR>



*BayScan Technologies LLC*

**CONFIDENTIAL**